

FORM 128  
5-63

USE PREVIOUS EDITIONS

Approved For Release 2002/10/16 : CIA-RDP69B00404R000100240009-0

MFG. 9-55

CLASSIFIED MESSAGE

TOP SECRET

DATE

ROUTING			
1	OXC	9	RB
2	1	10	OSA
3	DAPS	11	
4	DM	12	
5	1	13	
6	1	14	
7	R4D	15	
8	11	16	

TO :

FROM :

ACTION:

INFO :

**PRIORITY**

IN 73802

*pls review and advise*  
*OSA 1-15 BF*

TO

TOP SECRET 130501Z CITE

CITE

PRIORITY INFO PRIORITY

OXCAR BLACKSHIELD OPS

*Return to OXC* 25X1A

1. DETACHMENT RECOMMENDS THAT ON ALL LEGS PACKAGE TURN ON BE INITIATED AT A POSITION THAT WILL ENABLE THE PILOT TO RECYCLE THE EQUIPMENT, SHOULD HE GET A PACKAGE FAILURE (LIGHT) INDICATION.
2. ON SOME LEGS, I.E., THE SECOND PENETRATION LEG OF BX6732, CURRENT TURN ON POSITION GIVES THE PILOT APPROXIMATELY ONE MINUTE OR LESS TO CONFIRM SATISFACTORY OPERATION OR INITIATE ABORT PROCEDURE. THIS ALLOWS LITTLE OR NO TIME TO ATTEMPT RECYCLING OF PACKAGE CONTROL, WHICH HAS PROVED SUCCESSFUL IN THE PAST.
3. TURN ON AT FL500 WILL ALLOW THE PILOT TO RECYCLE EQUIPMENT A NUMBER OF TIMES, AND IF PACKAGE IS INOPERATIVE TO INITIATE ABORT AT A POINT THAT WOULD PRECLUDE ENTRY INTO DENIED TERRITORY. FL500 IS ALSO RECOMMENDED BECAUSE IT COINCIDES WITH ANOTHER ACTION POINT (EWS ON).
4. THIS PROCEDURE IS RECOMMENDED ONLY WHEN THERE IS SUFFICIENT PACKAGE MATERIAL TO WARRANT EARLY TURN ON, I.E., PACKAGE RUN TIME NOT

TOP SECRET


GROUP 1  
EXCLUDED FROM AUTO-  
MATIC DOWNGRADING  
AND DECLASSIFICATION

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.

Approved For Release 2002/10/16 : CIA-RDP69B00404R000100240009-0

25X1A

IN 73802




T O P S E C R E T

PAGE 2

TO EXCEED SIXTY FIVE (65) MINUTES.

25X1A

5.



(PACKAGE I) IS IN COMPLETE AGREEMENT WITH  
RECOMMENDED PROCEDURE.

T O P S E C R E T

TOR: 130546Z NOV 67

T O P S E C R E T